INDEPENDENT

BATTERY CERTIFICATE




CERTIFICATE NUMBER: 0DFC78B8-BEC8-436A-9A3D-AE658530B54F

VEHICLE


BRAND: Chery MODEL: E5 - 61 kWh **MILEAGE:**

VIN: LNNABDBF6RDF78805

DATE AND TIME: 28.10.2025, 12:41:19 EXECUTED BY: Henley Cars Ltd t/a



RESULTS **WLTP RANGE**



Battery Management System (BMS) - analysis failed × Battery Sensor - analysis failed × Battery Measurements - analysis failed × Battery Cell Voltages - analysis failed × Vehicle Communication - warning detected



EVALUATION

INCONCLUSIVE - BATTERY HEALTH UNDETERMINED

he detailed battery diagnosis with the AVILOO FLASH test failed because not all requirements were met during the measurement. For Details scan the QR code.

For assistance, please contact AVILOO Customer Management.

horas Reico

Dr. Marcus Berger, CEO



Vehicle detected.

Analyzing data.

Analysis completed.

Starting data acquisition. Finished data acquisition.

Voltage Sensor	×
Current Sensor	×
Temperature Sensors	×
Cell Voltage Sensors	×

	Value	e Status
вмѕ	BMS State of Charge (SoC)*:%)
	SoC calculation accuracy:	×
m	BMS State of Health (SoH)*:)
	SoH calculation accuracy:	×

MENTS	4	Min	Max	Delta	Status
H	Battery Temperature	°C	°C	°C	×
REM	Cell Voltage	V	V	mV	×
SUI	Pack Voltage	V			
MEASURE	Average Current	A			

MESSAGES

0DFC78B8-BEC8-436A-9A3D-AE658530B54F

Analysis failed because not all necessary signals were received during data acquisition. Please repeat the test. If the problem persists, please contact AVILOO Customer Management.

SENSORS

*The values shown here were not calculated by AVILOO but correspond to the values read out from the battery management system (BMS) and were calculated by the manufacturer. AVILOO therefore assumes no liability for their accuracy.

DISCLAIMER: The test result includes the currently calculated state of health (SoH) of the drive battery. The determination is based on data provided by the vehicle. These are evaluated by AVILOOs algorithms using statistical and analytical models. Manipulation of the data in the control unit leads to an incorrect result. The indicated SoH has a technically induced fluctuation range (deviation) of no more than 3% in at least 95% of reference measurements. It should be noted that this tolerance applies to the SoH determination at the cell level and not to the SoH of the entire battery. This is because the state of charge of individual cells may vary, which can negatively affect the current SoH of the battery. However, this can be compensated by the Battery Managament System (BMS) or during a calibration. The result reflects the condition of the battery at the time of the test. No conclusions can be drawn about the future state of health of the battery from this. Statements about mechanical damage or external influences are not part of this diagnosis.