INDEPENDENT

BATTERY CERTIFICATE



CERTIFICATE NUMBER: FEACCA81-7DFC-426C-96F7-B245046E7A26

VEHICLE

RESULTS


BRAND: Chery MODEL: E5 - 61 kWh MILEAGE:

VIN: LNNABDBF0RDF19250

DATE AND TIME: 31.10.2025, 06:36:04 EXECUTED BY: Henley Cars Ltd t/a



WLTP RANGE



×
×
×
×
Ţ



INCONCLUSIVE - BATTERY HEALTH UNDETERMINED

The detailed battery diagnosis with the AVILOO FLASH test failed because not all requirements were met during the measurement. For Details scan the QR code.

For assistance, please contact AVILOO Customer Management.

horans Reige

Dr. Marcus Berger, CEO



EXECUTION PROTOCOL

MESSAGES

G√		Gross	Net (Nominal)	Usable	
ER	Current:				
Z W	New:				
		1			

щ		WLTP	Typical
RANGE	Current:		
2	New:		

AVILOO Box connected.	06:36:00	
FLASH Test started.	~	
Vehicle detected.	~	
Starting data acquisition.	~	
Finished data acquisition.	~	
Analyzing data.	~	
Analysis completed.	~	

Voltage Sensor	×
Current Sensor	×
Temperature Sensors	×
Cell Voltage Sensors	×

	Value	Status
	BMS State of Charge (SoC)*%	
BMS	SoC calculation accuracy:	×
m	BMS State of Health (SoH)*:%	
	SoH calculation accuracy:	×

SL	4	Min	Max	Delta	Status
N H	Battery Temperature	°C	°C	°C	×
Z E E	Cell Voltage	V-V	V	mV	×
MEASUREMENTS	Pack Voltage	V			
4	Average Current	A			

Analysis failed because not all necessary signals were received during data acquisition. Please repeat the test. If the problem persists, please contact AVILOO Customer Management.

SENSORS

*The values shown here were not calculated by AVILOO but correspond to the values read out from the battery management system (BMS) and were calculated by the manufacturer. AVILOO therefore assumes no liability for their accuracy.

DISCLAIMER: The test result includes the currently calculated state of health (SoH) of the drive battery. The determination is based on data provided by the vehicle. These are evaluated by AVILOOs algorithms using statistical and analytical models. Manipulation of the data in the control unit leads to an incorrect result. The indicated SoH has a technically induced fluctuation range (deviation) of no more than 3% in at least 95% of reference measurements. It should be noted that this tolerance applies to the SoH determination at the cell level and not to the SoH of the entire battery. This is because the state of charge of individual cells may vary, which can negatively affect the current SoH of the battery. However, this can be compensated by the Battery Managament System (BMS) or during a calibration. The result reflects the condition of the battery at the time of the test. No conclusions can be drawn about the future state of health of the battery from this. Statements about mechanical damage or external influences are not part of this diagnosis.